

Job Description



POSITION TITLE	Machinist
BUSINESS/LOCATION	Bohemia, NY
POSITION REPORTS TO	Operations Manager
QUALIFICATIONS	
<ol style="list-style-type: none">1. 3-5 years experience with CNC machines (Lathes and Mills)2. Ability to run machine, measure parts, and make necessary machine / program adjustments3. Ability to perform needed machine adjustments, insert changes, and set-ups4. Ability to read and understand Engineering Drawings5. Ability to work in team environment, and ask questions if needed6. Ability to work independently to complete assigned tasks and responsibilities	
EXPECTATIONS / JOB DUTIES	
<ol style="list-style-type: none">1. Move and stage material as appropriate for the machine centers2. Set-up, run, and Inspect production parts3. Maintain clean and safe work area by following procedures and complying with written and verbal instructions4. Support other areas within factory as needed5. Communicate production status to management <p><i>* Ability to maintain regular, punctual attendance consistent with company policies</i></p> <p><i>* Must be able to lift and carry up to 50 pounds, work in a fast-paced environment with repetitive motion, clutch, lift, grab, bend, stoop, push and pull with no difficulties, be on feet during work shift, and clearly communicate issues</i></p>	
BENEFITS	
<ol style="list-style-type: none">1. Medical, Dental and Vision Care Plans2. Flexible Spending Account3. Paid Time Off4. 401(k) Plan	